
## SEAL KIT FITTING INSTRUCTIONS PEC-50 ELECTRICAL CONDUIT CABLE ENTRY





Mark out position for electrical cable entry seal.

**NB:** The electrical cable entry seal should be positioned in the middle of a sump panel and when fitted it should be perpendicular to the sump wall and the conduit must enter the electrical cable entry seal perfectly aligned.



Assemble the electrical cable entry seal as shown ensuring that the gasket is positioned under the flange of the bulkhead fitting on the outside of the sump.





- 2 Using a drill piloted 73 mm diameter hole saw cut the correct size hole in the sump wall.
- A Initially hand tighten the lock nut until it is hand tight (ensure that the locking screw is accessible post installation), then using the supplied box spanner tighten the lock nut an additional 1/4 1/2 a turn. DO NOT OVER TIGHTEN AS THIS MAY DAMAGE THE FITTING.
  A THE FITTING.
  A THE FITTING.
  A THE CONDUCTION OF THE POST OF T